

Location: \_\_\_\_\_



**MI-SPF-100**

**WATER CLOSET  
REPAIR FLANGE**




**Specification:** MIFAB®'s MI-SPF-100 fabricated 10 gauge steel, powder epoxy coated water closet repair flange with alignment slots.

**Function:** MIFAB's MI-SPF-100 is used to repair broken toilet flanges. It permits the repair of broken toilet flanges without having to replace the entire toilet flange. Simply install the MI-SPF-100 under the broken area of the closet flange and tighten the nut. Applicable for all cast iron, plastic, copper and brass toilet flanges.



**MI-SPF-100**

**Application image  
MI-SPF-100**



Install the MI-SPF-100 here,  
underneath the nut.

CALIFORNIA PROPOSITION 65 WARNING. This product contains chemicals known to the State of California to cause cancer and birth defects or other reproductive harm.

Job Name: \_\_\_\_\_

Page No: \_\_\_\_\_

Section No: \_\_\_\_\_

Contractor: \_\_\_\_\_

Schedule No: \_\_\_\_\_

Purchase Order No: \_\_\_\_\_